SITE SAFETY PLAN September 3, 1980 PREPARER: Rod Bloese American Chemical Service, Inc. LOCATION: Griffith, Indiana TDD NO.: F5-8008-12A INVESTIGATIVE OBJECTIVE(S): Familiarization with site and determination of disposal PROPOSED DATE OF INVESTIGATION: Sept. 9, 1980 COMPLETE X PRELIMINARY BACKGROUND REVIEW: OOCUMENTATION/SUMMARY: OVERALL HAZARD SERIOUS MODÉRATE X UNKNOWN SITE/ WASTE CHARACTERISTICS LIQUID [X] SOLID X · SLUDGE 🔽 GAS ASTE TYPE(S): HARACTERISTIC(S): CORROSIVE X IGNITABLE X VOLATILE X RADIOACTIVE REACTIVE X TOXIC X UNKNOWN X OTHER 'ACI' TY DESCRIPTION: SIZE Approx. 6 acres BUILDINGS None TOPOGRAPHY Berm around site, uneven topography PRINCIPAL DISPOSAL METHOD (type and location) __buried_drums_and_sludge, area_fill_ UNUSUAL FEATURES (dike integrity, power lines, terrain, etc.) STATUS (open, closed, unknown) closed Railroad track to the north ISTORY (worker or non-worker injury; complaints from public; previous agency action): no worker injuries, no public complaints, USEPA conducted on-site_investigation, EEI_ off-site reconnaissance revealed no hazards HAZARD EVALUATION The American Chemical Service (ACS) site is located adjacent to the active Griffith municipal landfill. The ACS sites has been inactive since 1975. USEPA personnel conducted an on-site investigation and collected leachated and soil samples on May 8 and 9, 1980. No complaints on the subject site are on file with the County Board of Health. Due to the site closure five years ago no public complaints, and no exposed wastes, the surface hazard is limited to leachate on the site. EPA Region 5 Records Ctr.

ECOLOGY & ENVIRONMENT, INC. FIELD INVESTIGATION TEA

	WORK PLAN INSTRUCTIONS
<u> </u>	** ,
PE	PUBLIC PERIMETER IDENTIFIED X ZONE(S) OF CONTAMINATION IDENTIFIED
	NOTES: Site controlled by berm and fenced city landfill
ΡE	c areas of special safety concern identified .
	LEVEL OF PROTECTION: A B C D X MODIFICATIONS: Hardhat with faceshield or safety glasses, 5-minute escape capsule, safety booties, rubber boots, coveralls, cotton underwear,
	rubber gloves.
	SURVEILLANCE EQUIPMENT AND MATERIALS: camera, metal detector,
	tape, wooden stakes
DΕ	CONTAMINATION PROCEDURES:
	HOT LINE LOCATION (initial): North access road
	COMMAND POST LOCATION (initial): North access road by railroad tracks
	PDS STATIONS: 1. rinse boots 2. remove boots
	3. rinse & remove rubber gloves 4. change clothing 5.
	EQUIPMENT AND MATERIALS/SPECIAL FACILITIES: Two wash
	tubs with detergent and water.
	Dispose wash water on site.
	1.
SI	TE ENTRY PROCEDURES:
01	TEAM SIZE: E & E 4 EPA STATE OTHER 1 (James Tarpo)
	ENTRY BRIEFING (date) September 8, 1980
	STATION DESIGNATION (name/responsibility): 1. Rod Bloese (Team Leader-
	Ellen Jurczak - Command Post Command Doct
	4. John Angelo (On-site Investigator) 5.
	6
	WORK SCHEDULE/LIMITATIONS: Work will be limited to familiarization
	of site and metal detection work.
	NOTES: The work should be completed in two (2) hours.

ACUTE EXPOSURE SYMPTOMS	· FIRST AID .		
<i>j</i> 1			
2			
3			
5			
	•		
6 OTHER	•		
HOSPITALS/POISON CONTROL CENTERS (additional language)			
2. Poison Control Center - Use Gary Methodist Ho	spital, 600 Grant, 866-4710		
3. Dr. Richard Freeman, Vanderbilt University (615) 322-4754 (0) 292-5256 (II)		
. 4.	292-5250 (11)		
5	·		
EMERGENCY TRANSPORTATION SYSTEMS (fire, police, ambulance) 1. Griffith Fire Department 115 N. Broad 924-3151			
2. Griffith Police Department 115 N. Broad 924-3141			
3.			
EMERGENCY ROUTES			
1. Arbocast South to Joliet, west to Route 30, w	est to "4 Corners" in Dyer, on left		
2			
3			
4			
EQUIPMENT CHEC	KOUT		
SCBA CYLINDERS CYLINDERS	EYE WASH UNIT [] FIRST AID KIT []		
APR CARTRIDGES	DRINKING WATER SUPPLY		
EXPLOSIMETER [PERSONAL CLOTHING		
O2 INDICATOR			
DRAEGER PUMP TUBES	DECONTAMINATION MATERIALS		
RADIATION SURVEY METER			
RADIATION CONTAMINATION METER			

1. EMERGENCY PRECAUTIONS:

I.